

CONN1 X-AXIS
Pin2 Step
Pin3 Dir


CONN2 Y-AXIS
Pin4 Step
Pin5 Dir

CONN3 Z-AXIS
Pin6 Step
Pin7 Dir

CONN4 A-AXIS
Pin8 Step
Pin9 Dir

CONN5 B-AXIS
Pin1 Step
Pin14 Dir

USB style B connector
supplying the +5V from PC.



5 AXIS parallel port breakout board